

Affected Models and Serial Numbers

Model	Serial Numbers	Model	Serial Numbers	Model	Serial Numbers
LT5IIC-LP	1906010641	LT5ITC-DW-HP	1906010259	LT561-DRW	1786271703
	1906052300	FT861-DRW	1786540132		1786290231
	1706061894	LT7ITC-DW-MP	1706111917		1786290232
	1706090968	LT961-DRW	1726478969		1786307328
LT7IIC-LP	1706070533		1726478970		1950473163
LT9IIC-LP	1706082536		1726961040		1786520812
LT7ITC-DW-UP	1706091242		1786318489		1786687365
FT8CIC-LP	1806012799		1826713843		1826849186
LT7ITC-DW-HP	1806111058		1950506443		1826849187
LT788-DW	1856315586		1856101730		1849014767
LT5CIC-MP	1906061556		1856237546		1856222458
	1706071010		1856237547		1856222462
RE761-DRWC	1956678795		1856339747		1956659779
	1956702786	1856339748	1856381646		
	1956756009	1856461507	1856528796		
	1886296970	1886125334	1856528797		
ET788-DWH	1926462229	1886137016	1856582765		
RE962-DRW	1956126012	FT862-DRW	1786566429	1956510269	
ADV361-CIC-LP	1906071784		1826327074	1956510270	
	1906071785	LT761-DRW	1726924575	1886183635	
ET598-DW	1966001169		1849090254	1949011611	
RE961-DRWC	1956440302		1849090255	1949011612	
	1926449457	VA861-DRW	1926416012	1949064038	
	1949237991		1926416016	1956463691	
	1956440305	LT962-DRW	1856492079	1956890861	
	1956525865		1856492081	1956890853	
1956440304	1906071116		1956890856		
RE561-DRWC	1956880059	LT9ITC-DW-HP	1906071117	LT7CIC-UP	1906010463
	1956947337		1906071117	LT7ITC-DW-UP	1906071265
				ADV261-RIE	1986026608