

**DEVICES AFFECTED - O<sub>2</sub>Vent T Faulty Adhesion Adjuster Assembly**

	<b>Appliance Number Upper</b>		<b>Appliance Number Upper</b>
1	T2234-01	31	T2373-1
2	T2234-02	32	T2373-2
3	T2266-01	33	T2374-1
4	T2266-02	34	T2374-2
5	T2267-01	35	T2375-1
6	T2267-02	36	T2375-2
7	T2274-01	37	T2391-1
8	T2274-02	38	T2391-2
9	T2276-01	39	T2401
10	T2276-02		
11	T2281-01		
12	T2281-02		
13	T2286-01		
14	T2286-02		
15	T2303-01		
16	T2303-02		
17	T2311-01		
18	T2311-02		
19	T2328-01		
20	T2328-02		
21	T2333-01		
22	T2333-02		
23	T2351-01		
24	T2351-02		
25	T2353-01		
26	T2353-02		
27	T2364-01		
28	T2364-02		
29	T2365-01		
30	T2365-02		