



## Product Safety Recall

ST-250 Braaap Motorcycle – ST250WO0022016



Sold in Australia between Jun 2015 and Jun 2016

### Defect:

The mandatory requirement is that a motorcycle must have each mechanical component accurately stamped and displayed for identification purposes according to regulation for ADR compliance.

The following parts have been incorrectly stamped for identification purposes.

- Fuel Tap
- Rear Master Cylinder Cap
- Tail light assembly

Display the ADR83 Stationary noise test information sticker

### Hazard:

The consumer is unable to verify the authenticity and manufacturing standards of these components and there is the possibility this could lead to the incorrect replacement of parts which may affect vehicle performance and compromise the safety of the rider.

### What to do:

Customers should immediately contact and visit their place of purchase and organize a time to have these components replaced at no expense.

### Contact Details:

For further information and enquiries customers can contact Braaap Motorcycles by phoning **Floyd Croucher** on 0439 434 525 or **Andrea Smith** on 0417 381 552

[www.braaap.com.au](http://www.braaap.com.au)  
[www.braaapuniversity.com](http://www.braaapuniversity.com)  
e: [sales@braaap.com.au](mailto:sales@braaap.com.au)

**See [www.recall.gov.au](http://www.recall.gov.au) for  
Australian Product Recall Information**