

Product Safety Recall

Breville Fast Slow Cooker (BPR200) Lid Gasket

Domestic programmable stainless steel electric pressure cooker.



Identification:

- Units sold between October 2010 and October 2015 through electrical retailers and department stores nationally.
- Production date code (PDC) **1034-1511** inclusive. The production date code can be found within the rating label. The rating label is located on the back of the unit.
- Only BPR200 units with a white silicone lid gasket are affected.

Defect:

People have been injured because pressure has built up and released unexpectedly when the white lid gasket has been inserted in the wrong orientation, and contrary to the instructions in the manual.

Hazards:

Scalding - incorrect fitting of the supplied white lid gasket may result in release of hot liquids.

Action Required:

Customers can continue to use the appliance safely by following these simple instructions:

1. Check that the lid gasket is installed correctly before each use. Instructions are provided in the appliance instruction manual and can also be found at <https://www.breville.com/au/en/support/Recall.html>.
2. Do not lean across the vent while depressurising.
3. Do not force the appliance open. After depressurising, it should be possible to open the appliance using one hand.
4. Do not move the appliance when under pressure.

Consumers should contact Breville on 1300 727 424 (8.30am - 5pm AEST, Mon - Fri), email recall@breville.com.au or visit <https://www.breville.com/au/en/support/Recall.html> to arrange a new lid gasket kit which will be sent by Breville, free of charge.

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**