

CAMALOT™ & CAMALOT™ ULTRALIGHT Safety Recall Notice

Recall for Inspection of Camalot™ & Camalot™ Ultralights



Salt Lake City, Utah (April 13, 2016) - Black Diamond Equipment, Ltd., in cooperation with the U.S. Consumer Product Safety Commission (CPSC), is voluntarily issuing a recall, subject to user inspection, of Camalot™ and Camalot™ Ultralight spring-loaded camming devices because some units may have been improperly assembled and may fail during use, potentially resulting in injury or death.

This recall concerns all sizes of Camalots™ (.3 to 6) produced between May 18, 2015 and March 9, 2016, with manufacturing codes between 5133 and 6067. This recall also concerns all sizes of Camalot™ Ultralights (.4 to #4) produced between November 10, 2015 and March 4, 2016, with manufacturing codes between 5309 and 6061.

In a very small percentage of Camalot™ and Camalot™ Ultralights, the axles connecting the cam lobes to the stem may not be properly riveted. This could cause the device's strength to be compromised, and could possibly come apart during use.

No accidents have been reported; however, in the interest of customer safety, Black Diamond has decided to voluntarily issue a recall, subject to user inspection.

If you own Camalot™ or Camalot™ Ultralights that fall within the scope of this recall, Black Diamond is requesting that you STOP USE IMMEDIATELY, and inspect them following the procedures outlined at the website below. If they fail inspection, please contact Black Diamond, and we will replace your Camalot™ or Camalot™ Ultralights free of charge.

BlackDiamondEquipment.com/recall

Black Diamond contact information: 1-800-775-5552 | recall@bdel.com