

**12-H-02 – Barina, Captiva, Epica, Viva – Brake Performance Test,
Newspaper Advertisement Text**

Scheduled: Weekly Papers- Day Month XX, 2012, Daily Papers – Day Month XX XX, 2012

Vehicle Safety Recall

In the interests of safety and customer satisfaction, Holden is alerting customers to a potential condition on certain Barina, Captiva (Series I), Epica and Viva vehicles.

Description of Problem

General Motors Company has identified a condition where, in some instances, these vehicles may experience a reduced brake performance and or a spongy low brake pedal due to a sticky valve within the Electronic Brake Control Module (EBCM). Holden is not aware of any instances of this condition occurring in Australia.

Vehicles Affected

Barina's built between 2009-2010, Captiva's built between 2007-2010, Epica's built between 2008-2010 and Viva's built between 2007-2008 within the following ISOVIN ranges are affected:

Model	Year	From	To
Barina	2009-2010	KL3S####1#B253789	KL3S####1#B112341
Captiva	2007-2010	KL3CD###J#B012509	KL3CD###J#B012293
Epica	2008-2010	KL3LA###J#B112086	KL3LA###J#B011772
Viva	2007-2008	KL3N###BJ#K485878	KL3N###BJ#K977652

Hash (#) above represents an alpha or numeric character not relevant to determining affected vehicles.

The ISOVIN number is located on the registration label or ISOVIN plate (refer to your Owners Handbook for details on the ISOVIN plate location).

Action Required

Registered owners of the affected vehicles will be contacted by letter outlining the process for arranging a free of charge inspection, brake fluid flush and a replacement EBCM if deemed necessary.

If you believe your vehicle may be affected or if you require any further information, please contact your nearest Holden Dealer or call the Holden Recall and Rework Assistance Line on 1800 632 826. This service operates 8am to 7pm EST Monday to Friday and 9am to 1pm EST Saturdays except National Public Holidays.