


ELECTRICAL SAFETY RECALL

DC Solar Isolator

Katko-NHP brand, Metal and plastic versions sold at Electrical Wholesalers

Switch Cat No
KDA-432/
KDM-432
(Side label)



All NHP DC Solar Isolator Switches type KDA-432 and KDM-432 have been recalled. This recall includes switches replaced as a result of a previous recall in February 2014.

Affected units would have been sold to electrical wholesalers or solar contractors/installers between July 2013 and 10th October 2014

DEFECT: The switch contact mechanism may overheat due to an internal fault; this could result in damage of the switch mechanism, internal arcing and potential damage to the enclosure and cables which could allow access to live parts.

HAZARD: Fire and electric shock hazard

WHAT TO DO:

Electrical Contractors/Installers:

Defective DC Solar Isolator switches type KDA-432 and KDM4-32 are required to be replaced. PV systems with these switches need to be shut down and safe isolation procedures need to be followed.

For further details contact NHP Electrical Engineering Products Pty Ltd by phone or email.

Home owner/consumer

Contact your electrical contractor that performed the installation ASAP to organise the replacement of the switch. For further information contact NHP Customer Service Centre

Customer Service Centre; Phone 1300 NHPNHP (1300 647 647) or email to nhpsales@nhp.com.au

Visit our web page www.nhp.com.au/recall for further details

Re-sellers: Cease supplying switches and arrange returns to NHP by contacting (03) 9368 4088 or email NHPReturns@nhp.com.au. Visit www.nhp.com.au/recall for further details.

**See www.recalls.gov.au for
Australian product recall information**