

# Product Safety Recall

## Polaris Sales Australia Scrambler XP1000

single seat 4 wheel All Terrain Vehicle



**Defect** Certain model year 2014 - 2017 Scrambler XP1000 models were not calibrated to enter safe mode in the event of a stuck throttle cable. In the event of a stuck throttle cable the ECU will illuminate the check engine light but will not limit engine RPM or vehicle speed.

**Hazard** In the event the throttle cable becomes stuck, the operator could lose control and have an accident causing injury or death.

**What to do** Consumers should not use their vehicle until it has been inspected and repaired by an authorised Polaris dealer. Owners will be contacted by mail at their Polaris-registered address and instructed to contact their local Polaris dealer to arrange for an inspection and repair of the vehicle.

**Contact details** The Polaris Customer Service Department can be contacted by phoning 03 9394 5610. Find your nearest Polaris dealership by visiting [www.polarisindustries.com.au](http://www.polarisindustries.com.au)

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**