

# Product Safety Recall

Disc Brake Rotors  
DBA4418, DBA4418S &  
DBA4418XS



Manufactured by Disc Brakes Australia Pty Ltd in 2013 - 2014  
Installed in selected Mitsubishi Lancer EVO  
model years 1998 - 2007

**Defect** If the disc brake rotor experiences a rapid change in temperature, such as during high speed braking in motorsports or similar extreme driving conditions, the rotor may fracture and separate, which may result in brake failure.

**Hazard** If the disc brake rotor fractures, the brake may not function correctly and may fail, posing an accident or injury risk to the vehicle occupants and other road users.

**What to do** Owners of affected vehicles should arrange to check the rotor number of their disc brake rotors. If the rotor is from the affected DBA4418 batch, the rotor should be replaced. Cost of replacement will be reimbursed by DBA.

Instructions for checking the rotor number can be found at <https://dba.com.au/home-welcome/dba4418s-mitsubishi-lancer-evolution-product-recall-information/>

**Contact details** For further information contact DBA on 1800 730 039, [inquiries@dba.com.au](mailto:inquiries@dba.com.au) or at [www.dba.com.au](http://www.dba.com.au)

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information