

PRODUCT SAFETY RECALL

Specialized Australia Pty Limited

ÖHLINS RXF 36 and RXF 34 AIR FRONT FORKS

Sold by Authorised Specialized Retailers between 2016 and 2018



Identification:

Affected forks were sold as aftermarket equipment and as original equipment on certain Specialized branded Enduro, Stumpjumper, Fuse, and Levo bicycles. Forks are black with “ÖHLINS” written in gold on each of the fork lowers. Affected forks have “RXF36” or “RXF34” written across the fork arch.

Defect:

The right-side topcap on some forks may not be adequately torqued which in some cases may lead to the topcap working itself free through riding.

Hazard:

The air cartridge may abruptly spring out of the stanchion tube causing a risk of injury to the rider.

What do to:

Stop using the affected forks immediately and return them to your nearest Authorised Öhlins or Specialized Retailer for a free repair. For inquiries, call Specialized Rider Care at:

1300-499-330

or online at www.specialized.com/au

See productsafety.gov.au for Australian product recall information

SAFETY RECALL NOTICE