

# ELECTRICAL SAFETY RECALL

## Specialized 1st Generation Turbo Levo and Kenevo Electric Mountain Bike Battery Packs

AFFECTED MANUFACTURE P/N		AFFECTED MADE DATE	AFFECTED MODEL EXAMPLE
B9JE2045F	B9JE2055F	G7 H7 I7 J7 K7 L7 A8 B8 C8 D8 E8 F8 G8 H8 I8 J8 K8 L8 A9 B9 C9	
B9JE2056F	B9JE2064F		
B9JE2065F	B9JE2077F		
B9JE2076F	B9JM2041F		
B9JE2098F	B9JM2042F		



### IDENTIFICATION:

Battery Pack Part Numbers:

B9JE2045F, B9JE2056F, B9JE2065F, B9JE2076F, B9JE2098F  
B9JE2055F, B9JE2064F, B9JE2077F, B9JM2041F, B9JM2042F

Made dates:

G7-L7, A8-L8, A9-C9

Batteries sold between 1 November 2017 and 1 November 2022 with the below listed bicycle models or purchased separately:

- Levo FSR model years 2016-2018
- Levo HT model years 2018-2021
- Kenevo FSR model years 2018-2019
- Specialized M1 Battery model years 2016-2021

### DEFECT:

Pressure washing can cause water to penetrate the seal around the battery's control panel and may cause a short circuit.

### HAZARD:

Risk of a fire, which may result in injury or property damage.

### ACTION REQUIRED:

Affected units should not be charged or used.

Consumers should return affected battery packs to their nearest authorised Specialized retailer for a repair, free of charge.

### For further information

Please direct all calls and any queries concerning this recall to  
**Specialized Australia on 1300 499 330 or [ridercare-au@specialized.com](mailto:ridercare-au@specialized.com)**

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for Australian product recall information