

Product SAFETY RECALL

Motorcycle Clip-on Handlebar

Renthal Gen1 & Gen 2 Clip-ons

Part Numbers

CL100, CL101, CL102, CL103, CL104, CL105, CL106, CL107, CL108,
CL109

Sold nationwide in motorcycle dealerships from 2009 to July 2017



DEFECT: The affected parts can fail due to stress corrosion cracking

HAZARD: If the defect occurs while riding the handlebar clamps can become loose on the fork leg causing the rider to lose control and crash.

ACTION REQUIRED: Customers should immediately stop using the product and return the part to Renthal for a free of charge replacement set

For further information

Please visit www.renthal.com/clipon-return for further information and instructions on how to register and return your part for a free of charge replacement set. If you have any questions you can email Renthal at cliponreturn@renthal.com

See www.productsafety.gov.au for Australian product recall information