

Product Safety Recall

Sierra Electric Fuel Pump Sierra Part No. 18-35433

Date Code	Date Sold
Date codes 192511 (YYDDMM) or newer	After 15 January 2020



Installed by Boat Bits, Cove Marine Pty Ltd, Davies Quality Marine, Dream Marine, Hi Tune Marine Pty Ltd, Hunts Marine Centre, Nautek Marine, Nautique Central NSW and North Track Machinery

Product description: Fuel pump may have been fitted as a replacement part to MerCruiser sterndrive and inboard V6, V8, 305/350/377/454/502 EFI marine engines during service or repair.

Defect: The O-ring in the product's wiring terminals is damaged and may leak fuel.

Hazard: If fuel leaks from the product, the boat's engine may fail and the boat may become stranded, increasing the risk of an accident or injury. There is also an increased risk of fire and/or explosion, which may result in serious injury or death.

What to do: Consumers should stop using their boat until a replacement electric fuel pump has been installed. Consumers should contact the dealer who supplied and fitted the product to organise to have the replacement installed, free of charge. Alternatively, consumers may contact BLA Distribution for a referral to a dealer who will arrange for the replacement to be installed.

For further information, consumers can contact BLA Distribution on 1300 252 725 (8am - 4:30pm AEST, Monday - Friday) or service@bla.com.au

**See productsafety.gov.au for
Australian product recall information**