


PRODUCT SAFETY RECALL

Bendix Brake Disc Rotor

Part Number BR2724, Batch Number 0720



Sold by FMP Group Australia Pty Ltd between 10 August 2020 - 12 July 2021 as BR2724 Ultimate rotor and within upgrade kits Ultimate 4WD BUK17 and Ultimate 4WD BUK17+2 Designed to be fitted to Toyota Land Cruiser VDJ200 / UZJ200 VX, Sahara 08/2015 - 2021 and Lexus LX570 08/2015 - 2021.

Defect: Due to a manufacturing error, the wall section of the disc brake rotor may not be thick enough in the neck area, which may crack.

Hazard: If the brake disc rotor should crack in use, the vehicle could experience a reduction in braking efficiency, increasing the risk of an accident causing serious injury or death to vehicle occupants and/or other road users.

What to do: Consumers should immediately stop using the affected product or vehicles that have been fitted with an affected product. FMP will contact affected consumers to provide instructions on obtaining a replacement or refund.

Where an affected product has been fitted onto a vehicle, FMP will arrange to have the disc brake rotor(s) replaced by a qualified mechanic, free of charge. Affected products that have not been fitted to vehicles may be returned to the place of purchase for a full refund.

Contact Details: For further information, consumers can contact the FMP Customer Call Centre on 1800 819 666.

See www.productsafety.gov.au for
Australian product recall information