

Product Safety Recall

Xtreme Performance Clutch Kits



Sold between 1 August - 30 November 2021

Part numbers: KTY24009-1A, KTY24009-1B, KTY24009-1C, KTY24009-1T, KTY24509-1A, KTY24020-1A

Defect: Due to an issue during manufacturing, the clutch kit may fail during use.

Hazard: If the clutch kit fails, it may increase the risk of an accident resulting in injury or death. It may also damage fuel lines, increasing the risk of fire.

What to do: Consumers with affected clutch kits have been contacted directly by Australian Clutch Services or their resellers. Consumers should immediately stop using the vehicle, and not restart the engine. Consumers should have the vehicle towed to a place of repair and contact Australian Clutch Services to arrange a replacement clutch kit.

Contact details: For more information, consumers can contact Australian Clutch Services by phone on 08 8300 5000, via email at sales@australianclutch.com.au or via Facebook <https://www.facebook.com/XtremeClutch>

See productsafety.gov.au for
Australian product recall information