

Product Safety Recall

Seatbelt Anchorage Bolt affecting APV Safety Products Aftermarket Seatbelts and Fitting Kits

Manufactured between 1st June 2018 and December 21st, 2018.



Defect: Fuji Fasteners Pty Ltd have initiated a recall of the seatbelt anchorage bolt as a result of an 'internal' defect. The bolt can be identified as 'silver with three raised lines' on the bolt head. Other bolts are not affected.

Hazard: The defect identified is isolated to one Grade 5 seatbelt anchorage bolt but cannot be identified by visual examination. In certain circumstances the bolts could fracture.

If the bolt fractures, the seat belt's performance could be compromised in a vehicle crash. APV Safety Products is not aware of any accidents or injuries related to the defect.

What to do: Check if you have an APV Safety Products seatbelt installed within your vehicle. **The Seatbelt Manufacturing Dates as found on the Seatbelt Label that require checking are from June 1st, 2018 to December 21st, 2018.**

Vehicles fitted with APV Safety Products Seatbelts and Buckles within this date range using the silver bolt type, with the unique markings on the head as shown above, should have the bolts replaced with new bolts supplied by APV Safety Products.

Detailed identification and replacement instructions are available from APV Safety Products.

Contact Details: If you identify a Silver Bolt Head design in your APV Safety Products vehicle seatbelt that was fitted after 1st June 2018 and with a manufacturing date prior to 1st January 2019, contact APV Safety Products on 1800 804 588 (Aust) or 0800 440 703 (NZ). Alternatively, email: recall@apvcorporation.com or contact the workshop or mechanic who installed the seatbelt. See: www.apvsafetyproducts.com for further information.

Required replacement bolts will be supplied at no charge including freight and reprocessing costs.

**See productsafety.gov.au for
Australian product recall information**