

Product Safety Recall

Trek Bicycle Corporation (Australia) Pty Ltd – Base bar on model year 2022 Speed Concept SLR bicycles & Bontrager Aeolus RSI VR-C handlebar/stems fitted on model year 2021 and 2022 Emonda SLR bicycles and supplied as an aftermarket part (model years 2020, 2021, and 2022)



Emonda



Handlebar



Speed

**Sold by Authorised Trek retailers between
5 June 2020 and 7 June 2022**

Base Bar on all model year 2022 Speed Concept SLR Bicycles (SLR 9, SLR 9 eTap, SLR 7, SLR 7 eTap, and SLR 6 eTap) and Bontrager Aeolus RSL VR-C Handlebar/Stems fitted on all model year 2021 (SLR 6, SLR 6 eTap, SLR 7, SLR 7 eTap, SLR 8, SLR 9 and SLR 9 eTap) and 2022 (SLR 6 eTap, SLR 7, SLR 7 eTap, SLR 9 and SLR 9 eTap) Emonda SLR Bicycles. The Handlebar/Stems were also supplied as aftermarket parts (model years 2020, 2021 and 2022).

Defect If overloaded, the carbon Base Bar and Handlebar/Stem can crack.

Hazard If the Base Bar or Handlebar/Stem breaks, the rider could lose control of the bicycle and fall, leading to serious injury.

What to do Consumers should immediately stop using bicycles installed with the affected Base Bars and Handlebar/Stems. Consumers can contact an authorised Trek retailer to make an appointment for a replacement Base Bar or Handlebar/Stem, when available.

Consumers can obtain further information by contacting Trek Bicycle Corporation (Australia) Pty Ltd by telephone on 02 6173 2400 or email: customerservice_australia@trekbikes.com

**See productsafety.gov.au for
Australian product recall information**