

# Product Safety Recall

## Dometic Marine Steering Cable

Affected models are:

- a) Malibu Response Models include the Response TXI.
- b) Malibu Wakesetter models include the 20VTX, 21LX, 22LSV, 23LSV and 23MXZ.
- c) Axis models include the A20 and T220



**Defect:** The retaining nut that is designed to prevent the boat's steering cable from detaching from the boat's rudder block may fail.

**Hazard:** If the retaining nut fails, this could lead to a loss of steering control of the boat. Steering loss may cause an accident, resulting in death or injury to the boat occupants or bystanders.

**What to do:** Consumers should contact their closest Malibu Boats dealer to arrange for repair, free of charge. Consumers should not use the boat until it has been repaired.

A list of Malibu and Axis Boat Dealers in Australia can be found here: <https://www.malibuboats.com.au/malibu-boats-specialists>

**Contact details:** For more information contact Malibu Boats Australia on 02 6040 1174 or via the online contact form at: <https://www.malibuboats.com.au/malibu-boats-specialists#contactus>

**See [productsafety.gov.au](https://www.productsafety.gov.au) for  
Australian product recall information**