

Product Safety Recall

DOMETIC (SEASTAR) MECHANICAL STEERING CABLES

| Date Code | Date sold |
|---|--------------|
| Date code 22116 - 22231 (formatted as YYDD) or newer | After May 22 |

HOW TO DETERMINE IF YOUR CABLE IS AFFECTED

Check the model type of your cable

Affected models:


Rotary Steering
SSC62 SS132 SSX176
SSC131 SS137 SSX177
SSCX64 SS147

Rack Steering
SSC124 SS141
SSC134 SS151
SSCX154

Kicker Cables
433



Cables are either heat stamped, or laser marked with their product information at the engine end of the cable.



Affected products are within:

YEAR "22"

and between
DAY range:

116 through 231
ONLY.

IMPORTANT

Product description: Dometic (Seastar) Mechanical Steering Cables

Defect: The retaining nut that is designed to prevent the boat's steering cable from detaching from the boat's engine may fail.

Hazard: If the retaining nut fails, this could lead to a loss of steering control of the boat. Steering loss may cause an accident, resulting in death or injury to the boat occupants or bystanders.

What to do: Consumers should contact the dealer who they bought the boat from to arrange for inspection and replacement of the cable if required, free of charge. Consumers should not use the boat until it has been checked and, if required, the steering cable is replaced.

Contact Details: For more information contact BLA Australia, Monday to Friday, 8am to 4:30pm AEST on 1300 252 725 or email service@bla.com.au

See productsafety.gov.au for
Australian product recall information