

Product Safety Recall

Trek Kickster Balance Bicycles
(bicycles without pedals)
Model Years 2013-2019



Defect: The clamp that holds the steer tube in place may break when over-tightened, due to uncontrolled die temperature of the aluminium during the manufacturing process.

Hazard: If the steer tube clamp breaks, the handlebars may come off the bicycle, this may result in a fall or injury to the child.

What to do: Consumers with affected Trek model bicycles should immediately stop using their bicycles and take them to a Trek retailer for inspection and repair.

Affected bicycles will be fitted with replacement clamps that hold both the steer tube and seat post (the clamps are interchangeable).

Contact Details: For further information, contact Trek Australia by telephone on 02 6173 2400 or email customerservice_australia@trekbikes.com

**See productsafety.gov.au for
Australian product recall information**