



Product Safety Recall

Mercury MerCruiser 4.5L & 6.2L Engines

Models Covered	Serial Range
All Mercury MerCruiser 4.5L & 6.2L Models: Sterndrive, Inboard & Towsport	2A636671-2A673383

Engine Identification Pictures

4.5L	6.2L
	

Defect:

Possibility of a crack in the fuel supply module in some engines that may result in a fuel leak. The fuel could ignite if present in the engine compartment.

Hazard:

A crack in the fuel supply module may allow fuel to leak inside the engine compartment presenting a fire hazard.

What to do

Immediately contact your authorised Mercury Marine MerCruiser Dealer to schedule a service appointment for the engine to be inspected and, if affected by the recall, for the fuel supply module to be replaced. When scheduling your service appointment, be sure to mention Mercury MerCruiser Service Bulletin 2019-10.

Contact details: Contact Mercury Marine Customer Service on 03 9791 5822 (Monday to Friday, 8.30am to 4.30pm AEST) or email merc.info@mercmarine.com

To locate your nearest Mercury Marine dealer, visit <https://www.mercurymarine.com/en/au/find-a-dealer/>

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**