

Product Safety Recall

ST-250 Braaap Motorcycle– ST250WO0062017



Sold in Australia between June 2016 and present.

Defect:

In some circumstances, the front fender bracket may fail.

Hazard:

If the defect occurs whilst in use, the front fender bracket may fail causing the front fender to become loose, posing an accident hazard to the rider or resulting in serious injury.

What to do:

Customers should immediately contact and visit their place of purchase and organize a time to have this component replaced at no expense to them.

Contact Details:

For further information and enquiries customers can contact Braaap Motorcycles by phoning **Floyd Croucher** on 0439 434 525 or **Andrea Smith** on 0417 381 552

www.braaap.com.au
e: sales@braaap.com.au
www.braaapuniversity.com

See productsafety.gov.au for
Australian product recall information