Affected products and manufacturing codes

Affected models:

Ultegra

- FC-6800
- FC-R8000

Dura-Ace

- FC-9000
- FC-R9100
- FC-R9100-P

Affected manufacturing codes:

- KF to KL
- LA to LL
- MA to ML
- NA to NL
- OA to OL
- PA to PL
- QA to QL
- RA to RF