

Product Safety Recall

Convair Prestigio Convection Panel Heater



- Black, white and mirror finishes
- Model and product numbers:
 - CPH01B 1500W black (Product no: 001449)
 - CPH02B 2000W black (Product no: 001463)
 - CPH01W 1500W white (Product no: 001456)
 - CPH02W 2000W white (Product no: 001470)
 - CPH02M 2000W mirror (Product no: 001494)
- Sold through electrical retailers from March 2011 to July 2012

Defect:

In some circumstances, the element connection may overheat and become detached. The detached 'live' connector could then come in contact with the unearthed rear metal panel.

Hazard:

If the defect is present the consumer could make contact with the 'live' rear panel, possibly resulting in an electric shock hazard.

What to do:

Consumers should stop using the heater immediately and contact Seeley International to arrange for a brand new product replacement.

Contact details:

Please contact 1300 586 138 or recall@convair.net.au

**See www.recalls.gov.au for
Australian Product Recall Information**