

Product Safety Recall

BLEND-X
PRO



The rating label can be found on the underside of this product showing the type BLM80 and the date code from 14x01 to 15x22

“x” can be a number from “0” to “9”



Kenwood Blend-X PRO Blender

Blender; model Blend-X PRO, type BLM80, manufactured from April 2014 and May 2015

Defect: Due to an inconsistency in the metal used in the manufacture of the lower blade of the blender, there have been instances where the blender blade has broken during routine internal testing.

Hazard: If the defect occurs, broken blade pieces may become mixed with food or drinks, posing an ingestion and / or choking hazard.

What to do: Stop using your blender and contact Kenwood to arrange a replacement blade assembly with a new and improved blades set.

Contact details: for more information contact

phone: 1-300-365-519.

online: www.blendxproblm800safetynotice.com

(or <http://www.kenwoodworld.com> in customer support section)

Australia Importer/Distributor

Company Name: De'Longhi Australia PTY LTD,

Address: Nexus Park, Unit 3, 43 Lyn Parade, Prestons, NSW, 2170,

Country: Australia

See www.recalls.gov.au for Australian product recall information