

# ELECTRICAL SAFETY RECALL

## Portable Electrical Adapter

Ampfibian RV-02MAX sold between 20/12/13 - 06/02/14 only

Picture or Sketch of product



### DEFECT:

Incorrect overload rating of supplied circuit breaker / RCBO (residual current device)

### IDENTIFICATION:

RV-02MAX products with 'C16' marked switches installed are affected. Identify effected product as pictured above.

Products with 'C10' marked switches are not affected by this notice.

These products were sold to electrical wholesalers, caravan and RV accessory outlets.

### HAZARD:

The defect may lead to a fire hazard and, if the insulation deteriorates, an electrical shock hazard.

### ACTION REQUIRED:

Check the RV-02MAX for the marking 'C16' as above. If 'C16' is marked on the units stop using product immediately and contact Ampfibian as soon as possible.

### For further information

Please direct all calls and queries concerning this recall to Ampfibian on **1800 342 426** or via email at [info@ampfibian.com.au](mailto:info@ampfibian.com.au).  
See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian product recall information