



## FLOS SPA – FLOS SKYGARDEN

F6410044, F6410047, F6410009, F6420044, F6420047, F6420009, F6420030

## What is the defect?

There may be a fault in the part of the light that bears the weight of the lamp, which may lead to the buckling of the lamp suspension system

## What are the hazards?

In the worst possible scenario, the light may fall and cause injury or damage property.

## What should consumers do?

Known customers who purchased SKYGARDEN lights between January 2008 and July 2016 will be contacted by email or mail. Arrangements will be made for a licensed electrician to visit and install a retrofit safety kit at no charge to the consumer. Once installed, the safety kit is not visible externally and there is no visible difference to the light.

For further information or to book a visit of an electrician to repair the affected SKYGARDEN light, telephone 02 9356 9900 Mon-Fri 9:00-5:30pm, or email <a href="mailto:skygarden@euroluce.com.au">skygarden@euroluce.com.au</a>

**Supplier:** FLOS SpA

**Traders who sold this product:** Euroluce Lighting Australia (Sydney, Melbourne,

Brisbane)

Space Furniture (Sydney) Design Farm (Perth)

Where the product was sold: Nationally

**Dates available for sale:** 1 January 2008, 1 July 2016

See productsafety.gov.au for Australian product recall information