

Product Safety Recall

Salton (Aust) Pty Ltd advises consumers that it is undertaking a voluntary recall on the George Foreman Stick Mixer model GFSM1 that have been available for sale in Australia and New Zealand between September 2009 and March 2010.

It is possible that the blender blade may break away from the **blender shaft**.

Consumers are advised to immediately stop using the **blender shaft attachment** and contact the Salton Customer Service Department on our toll free number **1800 190 400** (Australia) or **0508 629 777** (New Zealand) for instructions concerning the return of the **blender shaft attachment** and receiving a replacement part. Batches affected are 0933, 0935, 0942, 0943, 0949. The company advises that the chopping bowl (including chopping blade), and the whisk do not form part of this product recall.

Salton (Aust) Pty Ltd
7 Chifley Drive
Chifley Business Park
Mentone Vic 3194
www.salton.com.au

Salton NZ Ltd.
PO Box 300 201
Albany, Auckland
New Zealand



See www.recalls.gov.au for
Australian Product Recall Information

rev_080410