



Affected HIN Range

Model	YM	HIN		Production Date		Affected
		From	To	From	To	
ARX1200T3	2002	JP-HPSA0005J102	JP-HPSA3548J102	29-Nov-2001	29-Mar-2002	3534
ARX1200N3	2002	JP-HPSB0003J102	JP-HPSB1506J102	13-Nov-2001	22-Mar-2002	1498
ARX1200T3	2003	US-HPSA0010J103	US-HPSA3429J103	20-Nov-2002	20-May-2003	3411
ARX1200N3	2003	US-HPSB0008J103	US-HPSB1087J103	10-Dec-2002	28-Mar-2003	1074
ARX1200T2	2003	US-HPSC0038J103	US-HPSC2017J103	24-Mar-2003	19-Jun-2003	1964
ARX1200T3	2004	US-HPSA0024L304	US-HPSA3255E404	12-Dec-2003	23-Jun-2004	3230
ARX1200N3	2004	US-HPSB0012A404	US-HPSB1991J404	20-Jan-2004	29-Oct-2004	1980
ARX1200T2	2004	US-HPSC0001F304	US-HPSC4320B404	20-Jun-2003	26-Feb-2004	4320
ARX1200N2	2004	US-HPSD0018J304	US-HPSD2177L304	22-Oct-2003	17-Dec-2003	2160
ARX1200T3	2005	US-HPSA0003J405	US-HPSA2685E505	21-Oct-2004	17-May-2005	2681
ARX1200N3	2005	US-HPSB0011A505	US-HPSB1630D505	25-Jan-2005	26-Apr-2005	1619
ARX1200T2	2005	US-HPSC0002E405	US-HPSC2703J405	24-May-2004	19-Oct-2004	2701
ARX1200N2	2005	US-HPSD0002E405	US-HPSD1411J405	24-May-2004	7-Oct-2004	1410
ARX1200T3D	2005	US-HPSE0012L405	US-HPSE2531E505	13-Dec-2004	31-May-2005	2520
ARX1200T3	2006	US-HPSA0001E506	US-HPSA5418E606	24-May-2005	11-May-2006	5418
ARX1200N3	2006	US-HPSB0001G506	US-HPSB3260F606	26-Jul-2005	6-Jun-2006	3259
ARX1200T2	2006	US-HPSC0001J506	US-HPSC0720L506	25-Oct-2005	6-Dec-2005	720
ARX1200N2	2006	US-HPSD0001L506	US-HPSD0360L506	6-Dec-2005	16-Dec-2005	360
ARX1200T3D	2006	US-HPSE0002G506	US-HPSE1261E606	20-Jul-2005	17-May-2006	1258
ARX1200T3	2007	US-HPSA0001E607	US-HPSA4320I707	16-May-2006	19-Sep-2007	4320
ARX1200N3	2007	US-HPSB0001G607	US-HPSB3240L707	18-Jul-2006	18-Dec-2007	3240
ARX1200T2	2007	US-HPSC0001I607	US-HPSC0360I607	6-Sep-2006	26-Sep-2006	360
ARX1200T3D	2007	US-HPSE0001F607	US-HPSE1800J707	22-Jun-2006	4-Oct-2007	1800
Total						54837