

Product Safety Recall

Vehicle Jack Assembly RG Colorado, Colorado 7 & TrailBlazer



Defect: Certain vehicle Jacks, sold by Holden Service Parts Organisation (HSPO) via Holden Dealers, as service replacements for the RG Colorado, Colorado 7 and TrailBlazer, may not have been fitted with the required AS/NZS2693 label which describes the safe and correct usage of the Jack.

Hazard: Incorrect use of the vehicle Jack may result in an increased injury risk to the consumer.

What to do: Consumers are advised to inspect their vehicle Jack for the label shown above. If the label is present, no further action is required. If the label is not present, consumers are invited to present their vehicle Jack to a Holden Dealer in order to have a label fitted.

Contact Information: Affected Holden customers are invited to contact either Holden Customer Care by phoning 1800 632 826, or their nearest Holden Dealer to arrange a replacement label to be fitted to the vehicle Jack assembly. Dealer contact details can be found by visiting the GM Holden website. www.holden.com.au/dealerlocator.

**See productsafety.gov.au for
Australian product recall information**