

## Product Safety Recall

### Sport Cap 2.0 sold with Klean Kanteen® Water Bottles

#### Product Description:

The **Sport Cap 2.0** sold with all Klean Kanteen® water bottles. Please note that it is only the Sport Cap 2.0 that is being recalled. The water bottle is not affected. Other caps sold with Klean Kanteen® bottles such as the loop, flat or sippy caps are not affected.

Consumers that have purchased Klean Kanteen bottles since May, 2010 may have already received the new High Impact Sport Cap that is not affected by this recall. You can tell the difference by looking at the cap and label. The new cap has a dull/matte finish and the label had a small silver sticker attached:



#### What is the Defect?

The spout tip of Sport Cap 2.0 is prone to breaking or cracking after being dropped.

#### What are the Hazards?

Pieces could dislodge in the mouth and present a choking or swallowing hazard.

#### What should Consumers Do?

Consumers that have purchased Klean Kanteen Sports Cap 2.0 should stop using the cap, remove the cap from the bottle and contact 1 800 102 806 (in Australia) as soon as possible to arrange a replacement cap at no charge. Klean Kanteen will replace the cap with a new High Impact Sport Cap at no charge to the consumer.

See [www.recalls.gov.au](http://www.recalls.gov.au) for

Australian Product Recall Information