

SAFETY RECALL NOTICE

PLEASE READ IMMEDIATELY

Dear Polaris *RZR* Owner,

In cooperation with the ACCC and Australian Consumer Law, Polaris Industries Inc. has issued a Safety Alert for some Model Year 2015 *RZR XP 1000* and *RZR XP4 1000* models.

Some 2015 *RZR XP 1000* and *RZR XP4 1000* vehicles may have been manufactured with an improperly routed fuel tank vent line which may cause the vent line to become plugged, kinked, or pinched. A kinked, pinched, or plugged vent line can cause the fuel tank to build pressure and expand. The expansion of the fuel tank may result in contact of the spinning prop shaft which may result in a fuel leak.

DO NOT OPERATE YOUR VEHICLE UNTIL THIS SAFETY BULLETIN HAS BEEN COMPLETED BY YOUR POLARIS *RZR* DEALER.

Your Polaris *RZR* dealer has been authorized to inspect the fuel tank vent system and make necessary adjustments to avoid fuel tank vent line restrictions and inspect the fuel tank if necessary. This work will be performed at no cost to you.

Contact your local Polaris *RZR* dealer at your earliest convenience to schedule an appointment to have the bulletin completed.

This notice was mailed to you according to our most current registration information. If you no longer own this vehicle, or if some of the contact information (such as your address or name) in this notice is incorrect, please contact your local Polaris *RZR* dealer to complete a transfer of ownership.

While your Polaris *RZR* dealer is in the best position to answer your questions, if you have any questions your dealer cannot address, you may call our Customer Service Department at: 03 9394 5610

We apologize for this inconvenience and assure you that we are committed to customer satisfaction and providing world class products for riders to enjoy.

Sincerely,



Lance Whitelock
Polaris Sales Australia