

21 April 2011



To whom it may concern,

Dear Sir/Madam,

**Re: Avanti Bicycle Company Trade notification:**

Please note the following details regarding an Australia wide Trade notification from the Avanti Bicycle Company.

**Models affected:**

- 2011 Avanti Circa 1
- 2011 Avanti Circa 2
- 2011 Scott CX Comp
- 2011 Scott CX Team

**Defect:**

The above models of bicycles have not been supplied with a 'front brake cable safety device' as per the requirements of the Pedal Bicycle mandatory standard.

**Stipulation in the 'Pedal Bicycles' mandatory standards guide needing to be satisfied:**

*"If the bike has cantilever brakes does it have a safety device fitted to prevent the stirrup cable from contacting the tyre?"*

**Potential hazard:**

In the absence of a front brake cable safety device, the sudden wheel stoppage caused by a front brake cable failure could result in injury.

**What to do:**

Consumers should stop riding the bicycles immediately and contact Avanti Bicycle Company to be directed to the nearest authorised dealer to have a front brake cable safety device fitted. Safety devices are expected to be available for fitting in store for free fitting from April 28, 2011.

**Contact details:**

Please contact Avanti Bicycle Company on 1300 883 305 or [ausrecall@avantibikes.com](mailto:ausrecall@avantibikes.com)

Yours Sincerely  
Avanti Bicycle Company

Russell Johnston  
**Head of customer service**