

SAFETY RECALL NOTICE

Specialized Flux and Stix Lights



Flux



Stix

Hazard: The headlights and taillights can overheat, posing fire and burn hazards.

This is a Safety Recall Notice regarding the following lights:

- Flux Expert and Elite Headlights
- Flux Expert Taillight
- Stix Comp and Sport Headlights
- Stix Comp and Sport Taillights
- Stix Sport Headlight and Taillight Combo

Remedy: Stop using the affected lights immediately. Flux Lights should be returned to an Authorized Specialized Retailer for repair (Flux Headlights) or replacement (Flux Taillights). Stix Lights should be returned to an Authorized Specialized Retailer for replacement. For any inquiries, call Specialized Rider Care at:

1300-499-330

or online at www.specialized.com/au

Specialized Australia Pty Limited

SAFETY RECALL NOTICE