



\*Title\* \*Name\* \*Surname\*  
Address 1  
Address 2  
Address 3..State..Post Code

**Your MINI – Chassis Number XXXXXXX**  
**Safety Related Recall: MINI R5x and R60 Cooper S**  
**Defect Code – 00 17 4701 00: Replace Exhaust Turbocharger Coolant Pump**  
**Production period: 03.2006 - 01.2011**  
**Commencement date: 30/03/2012**

Dear \*Title\* \*Surname\*

We have obtained your address details via the Australian national VIN registry as being the current registered owner of the above mentioned MINI vehicle. BMW Germany has notified us of a product safety recall that affects your vehicle.

Quality monitoring at BMW Group has revealed that a short circuit may occur on the Turbo Charger's additional electric coolant pump in the engine compartment. The cause is dissolved plastic additives in the coolant pump for the exhaust turbocharger. At high temperatures, the deposited plastic additives may cause a short-circuit, which in very rare cases may cause overheating and scorching on the coolant pump. As such, the possibility of a fire in the engine compartment, or in the vehicle itself, cannot be completely ruled out.

To ensure that this area of your vehicle is in perfect working order, it is therefore necessary to replace the additional coolant pump on your vehicle. We ask that you **contact your preferred Authorised MINI or BMW Dealer** as soon as possible to discuss a suitable appointment time. The inspection and repair will take approximately 1 hour to complete and will be free of charge.

If you are no longer the registered owner of this vehicle, we would appreciate your advice of the current owner details. Alternatively, we ask that you let us know if your vehicle is no longer in service.

We sincerely appreciate your understanding and assistance in this safety recall action. Please accept our apologies for any inconvenience that may be caused as a result of this matter.

If you have any questions regarding this, please contact your preferred BMW / MINI Dealer or BMW Group Australia on 1800 813 299.

Yours sincerely

Colin Batten  
**Customer Relations Manager**

Company  
BMW Australia Ltd  
A.C.N. 004 675 129  
A.B.N. 11 004 675 129

BMW Group Company

Postal address  
P.O. Box 745  
Mulgrave, Vic. 3170

Company address  
783 Springvale Road  
Mulgrave, Vic. 3170

Reception  
+61 (0) 3 9264 4000

BMW Customer  
Interaction Centre  
Telephone  
133 BMW  
(133 269)  
Fax  
1800 350 528

Email  
info@bmw.com.au

Internet  
www.bmw.com.au  
www.mini.com.au

Chairman  
Guenther Seemann

Managing Director  
Phil Horton

Director – Finance &  
Administration  
Peter Buchauer