

Product Safety Recall

MITAS SPORT FORCE MOTORCYCLE TYRES FIVE SIZES

Products affected

120/70 ZR17 (58W) TL SPORTFORCE MITAS
150/60 ZR17 (66W) TL SPORTFORCE MITAS
160/60 ZR17 (69W) TL SPORTFORCE MITAS
180/55 ZR17 (73W) TL SPORTFORCE MITAS
190/50 ZR17 (73W) TL SPORTFORCE MITAS
Sold in Australia between April and July 2014.
DOT Codes 0114 to 2614



Defect

Mitas has detected that during sustained high speed riding a bulge may appear on the tread of the tyre causing vibration and, in the most extreme of cases, some of the tread may become detached. This problem has been simulated in controlled and very severe test conditions.

Hazard

If the defect occurs, the tyre may fail and poses a serious risk injury to the rider.

What to do

Cease using the tyre immediately. Contact your dealer to arrange the removal of the tyre and a refund.

Contact details

Contact the dealer that supplied your tyres. If you are unable to contact your dealer, contact the distributor directly on 1300 733 031 or email@motorcycletyres.net.au.

See www.recalls.gov.au for
Australian Product Recall Information