

# ELECTRICAL SAFETY RECALL

## Moretti 11 Fin Oil Column Heater

Model No. MC35B2, Batch 12/16 (OLN 9532, OLN 9539)



### IDENTIFICATION:

Check for unit identification details - **Batch Code** or **OLN Code** - on the rating label located on side of the front panel.

Affected heaters have **Batch Code 12/16** and **OLN 9532** or **OLN 9539** and were sold through **BUNNINGS** nationally in 2017.

Other batches of this model (MC35B2) are not affected by the recall.

### HAZARD:

The heater may rupture when turned on and allow hot oil to spray out, causing scalding and burns.

### ACTION REQUIRED:

Stop using the heater immediately and return it to the nearest Bunnings store as soon as possible for a full refund.

### CONTACT DETAILS:

For any further information, please contact Yale Prima Call Centre on **1300 366 155** in Australia or **0800 111 727** in New Zealand.

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information