

# ELECTRICAL SAFETY RECALL

## DC Solar Isolator

**NHP-KDA-432 and KDM-432**

**Metal and plastic versions sold at Electrical Wholesalers**



NHP DC Solar Isolator Switches with date codes from x0113 to x3813 (x can be any number between 1 & 5) have been recalled. Note that the last four digits are critical to identify the affected product. Switches with date codes x3913 and above are not affected. These date codes are only labelled internally and should only be accessed by an authorised electrical contractor.

Affected units would have been sold to electrical wholesalers or solar contractors/installers between July 2013 and February 7<sup>th</sup> 2014.

**DEFECT:** The switch may still be 'ON' even when the handle is indicating 'OFF'.

**HAZARD:** There is a risk of electric shock to the electrical contractor during maintenance and installation.

### WHAT TO DO:

#### Electrical contractors/Installers:

Defective switches are required to be replaced. For further details contact NHP Electrical Engineering Products Pty Ltd by phoning (03) 9368 4088 (during business hours) or visit [www.nhp.com.au/recall](http://www.nhp.com.au/recall).

**Re-sellers:** Cease supplying switches with affected date codes and arrange returns by contacting (03) 9368 4088 or email [NHPReturns@nhp.com.au](mailto:NHPReturns@nhp.com.au). Visit [www.nhp.com.au/recall](http://www.nhp.com.au/recall) for further details.

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian product recall information