

ELECTRICAL SAFETY RECALL

DC Solar Isolator

"PVPower" branded XPDCISO1000V32A DC Isolator



PVPower
brand mark

"PVPower" branded DC Isolator, part number XPDCISO1000V32A.

Sold through electrical wholesalers or direct to solar contractors/installers between August 2012 to August 2013.

DEFECT: Product internal fault, where a high resistant connection may form

HAZARD: RISK OF FIRE

There is a risk that the DC isolator may overheat and, in some cases, cause fire.

WHAT TO DO:

Electrical Contractors/Installers

Shut down the PV system. The DC Isolators are required to be replaced.

For a replacement program contact DKSH by phoning 1800 006 137 (during business hours), visiting <http://www.dksh.com.au/recall> or emailing recall.au@dksh.com.

Wholesalers/Resellers

Cease supplying PV Power DC Isolators and arrange returns by contacting 1800 006 137 or emailing recall.au@dksh.com. Visit <http://www.dksh.com.au/recall> for further details.

For further information

Please direct all calls and any queries concerning this recall to DKSH by phoning 1800 006 137 (during business hours), emailing recall.au@dksh.com or visiting <http://www.dksh.com.au/recall>.

See www.recalls.gov.au for
Australian product recall information