

Product Safety Recall



Stitched Sheaths for Gerber® Bear Grylls Parang Machete (Model Nos. 31-000698 and 31-002289)

Sold at Camping and Outdoor Equipment Retailers beginning in February 2012

Defect The Parang machete can cut through the stitching of the sheaths when the blade is taken from or replaced in the sheath. This issue applies only to stitched sheaths, which have only stitching on the curved side of the sheath and a total of 7 rivets.

Hazard Should the blade cut through the stitching of the sheath, this would pose a laceration hazard.

What to do If you have a Gerber Parang that came with a stitched sheath, stop using it immediately, store the Parang machete in a safe area away from children, and contact Gerber on the below details to learn how to return your stitched sheath for a free replacement fully-riveted sheath.

Contact Details You can contact the Gerber recall hotline at 1800 090 292 or visit Gerber's website: www.gerbergear.com.

See www.recalls.gov.au for
Australian Product Recall Information