

Product Safety Recall

WHEEL TRIM - HOLDEN MONARO GTS

Sold at Rare Spares and automotive stores Australia-wide and online between 4 January 2008 and 18 October 2011.

Identification: Wheel Trim (black centre - WT1003) for HG Monaro GTS, and Wheel Trim (red centre - WT1002) for HK HT Monaro GTS, supplied in set of 4.



Defect: The outer part of the Wheel Trim can move slowly over time, resulting in the outer part of the Wheel Trim rubbing on and cutting into the tyre valve stem.

The defect may occur only in Wheel Trim sets purchased between 4 January 2008 to 18 October 2011. Wheel Trim sets purchased from March 2012 are not affected.

Hazard: A cut in the valve can cause loss of air in the tyre tube, resulting in a flat tyre.

What to do: Affected consumers should contact RSP to arrange the return of their Wheel Trim for a free replacement set.

Contact details:

Lance Corby
RSP Automotive & Industrial Pty Ltd
Ph: (03) 9305 4000
Email: recalls@rsp.net.au
Web: www.rsp.net.au

See www.recalls.gov.au for
Australian Product Recall Information