


Product Safety Recall

dusk Australasia takes product safety very seriously and wishes to advise Customers of a product recall of the "Holly" tealight holder range.



Holly Tealight Holders

Stock numbers 6109, 6111, 6112, 6113, 6115, 6137
Sold at dusk stores between November 3rd 2010 and 21st January 2011.

Defect

In some circumstances the leaves and beads are positioned incorrectly.

Hazard

In rare cases if the candle flame comes in contact with one of the decorative leaves it may ignite causing a fire hazard. dusk Australasia, to date, has not received any reports of injuries associated with this issue but doesn't want anyone exposed to unnecessary risk. This recall is issued in accordance with the Trade Practices Act 1974 - Consumer Protection Notice No. 14 of 2010 - Temporary Ban on Goods - Legislative Instrument - F2010L03283

What to do:

Customers are asked to immediately stop using the product and return it to your nearest dusk store for a replacement or full refund, whether you have a receipt or not.

dusk Australasia apologises for any inconvenience caused.

Contact Information: For additional information contact your local dusk store or phone Mon-Fri between 8am and 5.30pm WST our Customer Support Centre on 08 9449 1900 or visit the dusk website www.dusk.com.au

See www.recalls.gov.au for
Australian Product Recall Information