

Electrical Safety Recall

CESCO GREENPOWER LPG/NG GENERATORS



Models: CC700, CC1200, CC1500, CC2000, CC2500, CC3000, CC4000.

Defects: 1. The DC battery recharge lead may be able to be inserted into a 240V socket. 2. The accessory AC plug doesn't comply with the current Australian Standard (for example: the plug pins are not properly insulated).

Hazard: Risk of Electric Shock.

If the lead is inserted into a 240V socket the battery clamps will become live, if touched can cause serious injury or death.

Dates the products were sold: 1st December 2010 – 4th May 2012

Where the products were sold: Nationally.

What to do: Consumers should immediately stop using the accessory AC plug and the DC battery charging lead, isolate the lead from use anywhere.

Remove and return the DC battery charging lead and the accessory AC plug (as pictured above) to Cesco Australia Ltd. Please call 13000 23726 and we will send a self-addressed postage-paid envelope to you to post the lead and plug back to us.

Contact details: Please call Cesco Australia Ltd on 13000 23726 or Send e-mail to info@cescoaustralia.com

See www.recalls.gov.au for
Australian Product Recall Information