

# Product Safety Recall



D0116 Light trailer slipper spring (used in D0115 assembly)  
D0108 Light trailer slipper spring (used in D0107 assembly)

Supplied by Martin's TRAILER PARTS  
July 2012 – December 2012

Defect: some springs have been found to have cracks in the minor leaves of the springs

Hazard: If spring leaves break, the axle becomes loose from the spring resulting in the axle moving backing and the trailer becoming dangerous.

What to Do: Consumers should inspect the springs and then contact their nearest store

Contact Details Bayswater 08 9279 5777  
O'Connor 08 9314 2222  
Wangara, 08 9302 2800  
[sales@trailerparts.net.au](mailto:sales@trailerparts.net.au)  
[www.trailerparts.net.au](http://www.trailerparts.net.au)

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information