

Product Safety Recall

Various Giant and Liv Bicycles

- 2015, 2016, 2017 Giant Stance 2 (sold from July 2014)
- 2017 Liv Embolden 2 Small and Medium size bikes only (sold from November 2016)
- 2017 Liv Tempt 1 (sold from July 2016)
- 2017 Giant ToughRoad SLR 0 (sold from August 2016)



Giant Stance 2
2015, 2016, 2017



Liv Embolden 2 2017



Liv Tempt 1 2017



Giant ToughRoad SLR 0 2017

Defect:

These models may not meet the relevant mandatory bicycle standard relating to chain guards and handlebar width.

Giant takes the compliance with relevant laws and safety standards incredibly seriously and is taking this action accordingly.

2015, 2016, 2017 Stance 2 - Handlebar width exceeds the maximum standard requirement.

2017 Embolden 2 - Handlebar width exceeds the maximum standard requirement.

2017 Tempt 1 - Bike is not fitted with a chain guard (all sizes) and the handlebar width exceeds the maximum standard requirement (Small and Medium sized bicycles only).

2017 ToughRoad SLR 0 - Bike is not fitted with a chain guard.

Hazard:

Relevant standards state that maximum overall handlebar width should not exceed 700mm.

Relevant standards require bicycles to have a chain guard to prevent entrapment of clothing or body parts.

No reports of injuries or incidents have been received by Giant.

What to do:

Owners/Consumers should contact the Authorised Giant Retailer who the bike was purchased from or any other Authorised Giant retailer to arrange a time to have the handlebars on their bicycle appropriately modified and or the necessary chain guide fitted.

If you require any further information on this matter please contact **Giant Bicycle Co. Pty Ltd**
1800 888 368 or info@giantbikes.com.au

Giant Bicycle Co. Pty Ltd Unit 7, 3-5 Gilda Court, Mulgrave, Victoria 3170

See productsafety.gov.au for
Australian product recall information