

# Product Safety Recall

## Recall Notice

### All SureLock II Rubber Weight Pocket Handles

Aqua Lung is conducting a recall of all SureLock II rubber weight pocket handles.

**Defect** A failure may occur due to separation of the rubber, cracking, tearing or breaking. If this were to occur during a dive, the weight pocket would be left engaged inside the buoyancy control device.

**Hazard**

If the defect occurs during a dive, this may pose a drowning hazard to the diver.



Both versions of rubber handle are being recalled



The replacement handle uses webbing instead of rubber.

**What to do:** Consumers should immediately stop using their BCs with Sure Lock II rubber weight pocket handles. Bring the pockets to your nearest authorized Aqua Lung Dive Retailer or Dive Center. They will be able to replace your handles for you while you wait, as changing handles is a quick process. The replacement is made under warranty and you will not incur any charges.

**Contact Details:** You can contact Aqua Lung on +61 3 9369 1992 or email us [salesaqz@aqualung.com](mailto:salesaqz@aqualung.com) or go to <http://www.aqualungpartnercenters.com/> for your nearest dealer.

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information