

Product Safety Recall

TOSHIBA 2-PIN AC ADAPTERS



2-pin AC Adapters Supplied with Certain Toshiba Notebooks

Supplied from July 2011 to October 2015 with Toshiba Notebook computers.

Affected part numbers are G71C0009S210, G71C0009T110, G71C0009T116 and G71C0009T210.

Defect: DC-IN plug of the AC adapter may overheat and cause a fire when the material contained within the plug deteriorates over time.

Hazard: Certain affected 2-pin AC adapters may pose a potential fire hazard.

What to do: Consumers should turn off their PC at the wall socket and unplug the 2-pin AC adapter immediately. Consumers should visit Toshiba's website www.mytoshiba.com.au/support/announcements to determine if the 2-pin AC adapter is affected and if so, register for a replacement AC adapter.

Contact Details: For further information consumers can contact Toshiba Client Solutions ANZ Pty Limited by calling 13 30 70.

**See productsafety.gov.au for
Australian product recall information**