



Product Safety Recall



Do you own this product?

Sun Trading Pty Ltd – Worldlawn King Cobra and Cobra Zero Turn mowers

Kawasaki general engines with voltage regulator (part no. 21066-0785) installed in King Cobra and Cobra Zero Turn mowers.

Affected King Cobra and Cobra mowers:

- WYK60FX921V5S – 60” King Cobra
- WYZ6027KW-H – 60” Cobra

Dates sold: 1 August 2022 – 1 January 2024



Why the product is recalled: The voltage regulator in affected Kawasaki general purpose engines, installed in select Worldlawn King Cobra and Cobra mowers, can malfunction. The affected mowers can catch fire at any time, even if the engine is off or not in use.

Hazard: There is risk of serious injury, death and/or damage to property if the voltage regulator catches fire.

Action required:



1. Stop using the affected mower until it has been repaired.
2. Disconnect the negative battery cable and secure it away from the negative battery post. If you are unsure on how to disconnect the battery, see the [Operator's Manual](#) or contact your [local Worldlawn dealer](#).
3. Contact your local Worldlawn dealer to arrange repair.



For more information contact Worldlawn via email doc@worldlawn.com.au or phone 07 5491 4569 (8:00am to 4:00pm, Monday to Friday).



Purchased from: Worldlawn dealers

PRA 2024/20164

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information