



# Product Safety Recall

## Do you own this product?



This is the portion of the manifold that has the potential to eject upon thread failure.

### Fluke Australia — 700HPPK / 700HPM, High Pressure Pneumatic Calibration manifold, 21 MPA

High-pressure pneumatic calibration manifold units included in 700HPPK test kits.

Affected models:

- 700HPPK-NPT – Fluke No. 4784838
- 700HPPK-BSP – Fluke No. 4810462
- 700HPPK-MET – 4810443

All units with serial numbers below 6516999 are affected by this recall. Units with serial number 6517000 and above are not affected by this recall.

Dates sold: 19 June 2017 – 22 November 2023



Serial Number Label



**Why the product is recalled:** The plunger nut threads on the calibration manifold may fail, causing the plunger assembly to be ejected from the manifold at high speed.

**Hazard:** There is a risk of serious injury to the user if they are struck by the ejected plunger assembly.



Follow [this link](#) to register your recalled manifold on the Fluke website. Please include your full contact information, including an email and shipping address.

Once registered, you will receive a return postage label so that it can be returned to FLUKE for repair and returned to you free of charge.



For more information, contact Fluke on 1300 135 853 (Monday to Friday, 8:30am – 5:00pm AEST) or by emailing [ordersanz@fluke.com](mailto:ordersanz@fluke.com)



Purchased from: Please see list of suppliers on the [Product Safety Australia website](#).

PRA2024/20252

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information