



Product Safety Recall

Do you own this product?

Solar panels manufactured between 2010 and 2012

Models:



- SCHOTT Perform POLY, 210-255 Wp
- SCHOTT Perform MONO, 180-270 Wp
- SCHOTT Power POLY, 210-290 Wp
- SCHOTT MONO, 180-190 Wp
- SCHOTT POLY, 155-240 Wp

Dates sold: From 01/01/2010



Why the product is recalled: The affected solar panels deteriorate and develop cracks on the back side of the panel, which could lead to live parts being exposed and could potentially make contact with live parts possible.

Hazard: Risk of death or serious injury as a result of potential electric shock or associated falls from height, if consumers come into contact with live parts of the solar panel.



1. If you think you have an affected solar panel contact ECORAN on info@ecoran.com
2. Include:
 - your full name
 - address where the panel is installed
 - the model of solar panel (if known)
 - the date and place of purchase (if known)
 - your best contact information
 - photos of your solar panel (**if it is safe to take them – do not take photos if it is not safe or easily done and do not take photos if you will have to come into physical contact with the solar panel**)
3. ECORAN will contact you to arrange an inspection and possible replacement or repair.



Contact
ECORAN
E-mail: info@ecoran.com



Purchased from: See traders list on www.productsafety.gov.au

PRA2025/20435

See productsafety.gov.au for
Australian product recall information